
Installation Guide


Picture 1




Parts List: as the picture shows.




Step 1:Lock the screws to fix the chassis, the place where the red arrow points is the screw hole, and the big round hole in the middle is the threading hole.



Step 2:Connect the driver and the power line, the ground line in the middle of the terminal can be connected freely on the left and right sides, and there is no need to distinguish between the neutral line and the live line.







Completion.