


Installation Guide

Picture 1



Parts list: Self-tapping screw C Size: M4*30MM.

Installation Time: 30mins. Number of Installers: 1. Installation Difficulty: 1.

Picture 2



Step 1: First remove the hanging plate pre-installed in the ceiling, and fix it on the ceiling with self-tapping screws.

Picture 3



Step 2: Connect the zero (blue wire), fire (red wire) and ground (yellow wire) wires to the terminal according to the diagram, and then connect them to the power supply at home.

Picture 4



Step 3: Fix the light body to the ceiling with 4 hanging plate screws.

Picture 5



Completion.